

# FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)  
(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 -1970)

1. Name of the Officer
2. Name of the School
3. Location with name of Education District/ Sub. District
4. Classification of Building as specified in column 4 of the application for fitness certificate and size.

Subhash G  
Santom Public School  
Eroakulam (Dist), Perumbavoor  
Ground Floor  
class rooms - 6m x 6m x 3.6m (15 Nos)  
principal room - 6m x 6m x 3.6m (1 Nos)  
office - 6m x 6m x 3.6m (1 Nos)  
library - 6m x 9m x 3.6m (1 Nos)

5. Period for which the certificate is issued

2022-23

6. Nature of defects, if any

- a) Foundation and basement
- b) Superstructure
- c) Doors and Windows
- d) Wood work wrought and put up
- e) Roof
- f) Flooring
- g) Miscellaneous (Cracks, etc.)

NIL

7. Any major defects noticed which will render the building unsafe in any manner

NIL

8. Whether maintenance works have been done properly

Yes

9. Whether the structure is sound or not for conducting classes

Sound under normal wind & weather condit

**Note :** 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

## CERTIFICATE

certified that the school building was inspected by me on 28/05/2022 and found to be fit / unfit to conduct classes, for the period 2022-23 for the reasons stated above. Sound under normal wind and weather condition.

Place : Vengoor

Date : 28-5-2022

Principal

Santom Senior Secondary School  
Vengoor - 683 546

Manager

Santom Senior Secondary School  
Vengoor - 683 546



Subhash G

Assistant Engineer  
L S G D Section  
Vengoor Panchayath (HQ)